


Correct Installation of the solenoid valve – all air conditioning systems

As part of product quality monitoring and analysis, we see an increased amount of solenoid valves **1102620A** which have been sent back with warranty claims asserted because of internal corrosion damage. These damages point to an incorrect positioning of the solenoid valves.


Against this background we would like to point out, that the installation of a new solenoid valve must be done mandatory according to the shown schema.

The electrical connection must **always facing down** to prevent an ingress of moisture through it.

Aluminum system



Copper system



IMPORTANT
The cable outlet must **always facing down.**